Civic House, 110 Trafalgar Street
PO Box 645, Nelson 7040, New Zealand

P (03) 546 0200
E rebecca.thiessen@ncc.govt.nz
nelson.govt.nz

20 February 2024

Kia ora,

POORMAN STREAM – STREAM BANK EROSION CONTROL

During the August 2022 weather event some of Nelson's rivers and streams suffered stream bank or stream bed erosion, and/or were inundated with flood debris. We need to remediate some of these areas to reduce the chance of the river flooding again and further damaging Council assets and/or private property.

We have identified an area of significant bank erosion along Poorman Stream, located behind 484 Main Road Stoke. Significant scouring of the bank has resulted in a risk to the regularly used walkway. The rock wall along the left side of the bank is to be repaired and stabilised using rock armouring (large rocks placed on the bank), starting on Monday 19 February 2024. The need for transporting large rock into the stream means the footpath beside the fire station will need to be closed for a short period of time.

The work will take around 2 weeks to complete (weather dependent).

The approximate area of repair is shown highlighted and circled in Figure 1 below.



Figure 1: Taken from Top of the South Maps.

If you have any questions or queries in relation to this work, please feel free to contact either me, by phone on 021 350763 or by email on rebecca.thiessen@ncc.govt.nz, or Marc Jary by phone on 027 3886077 or by email on mjary@nelmac.co.nz.

There may be some noise associated with this work, so we apologise for any inconvenience that this may cause.

We appreciate your patience while this work is completed.

Yours sincerely,

Rebecca Thiessen

Project Manager

Nelson City Council